

AC00B 4X4 6146 Power Supply for Clark

***Note: Filaments should be on 1 Min. before B+ is Applied.**

