



NOTES:

- 1) ALL RESISTORS 1/2W UNLESS OTHERWISE NOTED
- 2) MOUNT PSA-2N AS FAR AWAY FROM POWER TRANS AS POSSIBLE AND ORIENT FOR BEST HUM NULL