


## step-up impedance from 50 Ohms



L1-L2 ganged. L3-L4 ganged.

Operated so that when L is called for, L1 and L2 are increased first to max. and then L3-L4 are increased.